





FlexClamp Plus



Clamping bracket

This universal clamping bracket with a 1/4" thread and practical base enables optimum use of cross line lasers. It provides versatile, damage-free attachment to a range of surfaces and facilitates easy adjustment of the height and position of the measuring device.

- Easy-to-adjust clamping bracket
- Versatile damage-free mounting options
- With base
- Height and position of the measuring device easily adjustable
- With 1/4" thread



TECHNICAL DATA

Material	Polymer
Max. Height	14,5 cm
Min. Height	9,1 cm
Tripod Connection	1/4" thread
Operating Conditions	-10°C ... 50°C, max. humidity 80% rH, no condensation, max. working altitude 4000 m above sea level
Storage Conditions	-20°C ... 70°C, max. humidity 85% rH
Dimensions (W x H x D)	105 mm x 135 mm x 88 mm x (without accessories)
Weight	212 g (without accessories)

